



VAN DYCK

MAESTRO COLLECTION





TUFTED LOOP PILE TILES

| | |
|--------------------|--|
| Pile Fibre: | 100% PFX Stain Shield Fibre |
| Backing: | Enduroback KR4 (Modified Recycled Bitumen) |
| Fibre weight: | 500gsm |
| Total weight: | 4100gsm |
| Total thickness: | 7mm |
| Protective Finish: | Stain Shield |
| Location grade: | Medium Commercial |
| Fire rating: | 3 |
| Width/Size: | 50 X 50CM |
| VOC Rating: | Meets requirements green star rating (GBCSA criteria) |
| Country of Origin: | Manufactured in South Africa from local raw materials. |



WATERFALL TEXTURE



WATERFALL STRIPE



CROSSHATCH SABLE



TETRIS PITCH



STRUCTURE JET

BILL OF QUANTITIES

Tiles: Maestro Collection tufted tiles with Enduroback KR4 made from 100% PFX Stain Shield Fibre in (design name), by Van Dyck Carpets, laid in accordance with the code of practice for the installation of textile floor coverings (SANS 10186).

Colour Variance

Care must be taken when ordering or installing carpeting in individual areas, as carpeting, like all textile products, is subject to shade variation between batches.

CAUTION:

Colour fastness to light: Dyes are selected for their performance and repeatability to commercial standards, but colours can fade when exposed to harsh, direct sunlight. Adequate precautions must be taken to protect the carpet against such exposure to prevent premature fading or damage.

Furniture

Place protectors or carpet off-cuts under furniture to prevent crushing of carpet pile and eventual damage to the backing. Rearrange furniture from time to time to allow pile to recover and change traffic paths. Use carpet protector mats for chairs with castor wheels.

SATISFACTION

Due to dye lot variations and machine settings, actual material may vary from the sample. However, this variation is kept within exacting standards as laid down by SANS 1415. Construction of some carpet may involve the occurrence of shift lines across the width of the carpet. Certain light sources shining across the surface may emphasise the effect of shadow lines. These are not a manufacturing defect and will not detract from the carpet's performance.

Maintenance

Enhance the performance and appearance of your carpet by following these steps: ● Use quality walk off mats. ● Vacuum thoroughly and frequently. ● Remove spills and marks immediately. ● General clean by a SETA Qualified Cleaner.

>> Helpful Hint

Whilst lighter colours in the range are extremely attractive, they are high maintenance. They show soil quicker than darker colours and need frequent cleaning. We accept no liability on soiling, as this is maintenance related and not a manufacturing defect.

